

VEHICLE INSPECTION REPORT

BODY CONDITION

Status:Medium Accident Reported
ACCIDENT AREA: Front Accident, Right Side Accident, Roof Top Accident, Rear End Accident

Body Repaint:YES
BODY REPAINTED PARTS: FRONT RIGHT FENDER, FRONT LEFT FENDER, FRONT RIGHT DOOR, FRONT LEFT DOOR, BACK RIGHT DOOR, BACK LEFT DOOR, ROOFTOP, BACK RIGHT FENDER, BACK BUMPER, BODY PROPORTION REPAINT

Body Scratches: YES
SCRATCHES PART: FRONT BUMPER, FRONT RIGHT DOOR, BACK RIGHT FENDER, BACK LEFT FENDER, BACK HOOD COVER, BACK BUMPER, BODY MULTIPLE DENTS AND SCRATCHES, BODY MINOR DENTS AND SCRATCHES

LIGHTS

R-HL:AVERAGE

L-HL:AVERAGE

R-RL:AVERAGE

L-RL:AVERAGE

BODY REPAIR COST: {:223} AED

MECHANICAL CONDITION

ENGINE COMPONENTS: BODY VIBRATION ON IDLE AND GEAR SHIFTING POSITION, ENGINE SOUND MORE NOISY, ENGINE SLIGHTLY MISFIRING, ENGINE MISFIRING, ENGINE SIGN OIL LEAKING, ENGINE LESS POWER, ENGINE DAMAGED

GEAR COMPONENTS: GEAR SHIFTING SHOCK, GEAR JERKING, GEAR IMPROPER SHIFTING, GEAR SHIFTING NOISY

MECH. REPAIR COST: {:231} AED

ELECTRICAL CONDITION

WINDOWS & SUNROOF FAULTS FRONT RIGHT - FAULTY, FRONT LEFT - FAULTY, BACK RIGHT - FAULTY, BACK LEFT- FAULTY

AC COMPRESSOR: AVERAGE
AC FILTER: AVERAGE
AC COOLING: AVERAGE
AC AIRFLOW: LESS AIR FLOW

EXTERIOR FAULTS: FRONT RIGHT HEADLIGHT NOT WORKING, FRONTLEFT HEADLIGHT NOT WORKING, BACK RIGHT LIGHT NOT WORKING, BACK LEFT LIGHT NOT WORKING

Battery Condition:GOOD

ELEC. REPAIR COST: {:242} AED

INTERIOR CONDITION

INTERIOR FAULTS: WARNING LIGHTS IN INFORMATION BOARD

ROOF CEILING CONDITION: GOOD

UPHOLSTERY CONDITION: GOOD

STEERING WHEELS CONDITION: GOOD

INTERIOR REPAIR COST: GOOD AED

CAR COMPUTER DIAGNOSIS

MECHANICAL DIAGNOSIS: YES

ELECTRICAL DIAGNOSIS: YES

COMP/DIAG REPAIR COST: {:258} AED

TYRES/SUSPENSION CONDITION

TYRES:GOOD

RIMS:GOOD

BRAKES:GOOD

SUSPENSION:GOOD

DIFFERENTIAL & BEARING: GOOD

TYRE/SUS. REPAIR COST: AED

Location:

Mercato Shopping Mall Jumeirah. Dubai- UAE

Page 1