

VEHICLE INSPECTION REPORT			
BODY CONDITION			
Status: Major Accident Reported ACCIDENT AREA: Right Side Accident, Roof Top Accident		Body Repaint: YES BODY REPAINTED PARTS: BONNET, FRONT RIGHT DOOR	
Body Scratches: YES SCRATCHES PART: BACK RIGHT FENDER, BACK LEFT FENDER, BODY MINOR DENTS AND SCRATCHES			
LIGHTS			
R-HL: AVERAGE	L-HL: AVERAGE	R-RL: AVERAGE	L-RL: AVERAGE
			BODY REPAIR COST: {:223} AED
MECHANICAL CONDITION			
ENGINE COMPONENTS: ENGINE MOUNTINGS WEAK, BODY VIBRATION ON IDLE AND GEAR SHIFTING POSITION, ENGINE SOUND NOISY, ENGINE SOUND MORE NOISY		GEAR COMPONENTS: NO FAULT	
			MECH. REPAIR COST: {:231} AED
ELECTRICAL CONDITION			
WINDOWS & SUNROOF FAULTS NO FAULT		AC COMPRESSOR: WEAK AC FILTER: AVERAGE AC COOLING: AVERAGE AC AIRFLOW: LESS AIR FLOW	
EXTERIOR FAULTS: FRONT RIGHT HEADLIGHT NOT WORKING, FRONTLEFT HEADLIGHT NOT WORKING, BACK RIGHT LIGHT NOT WORKING, BACK LEFT LIGHT NOT WORKING		Battery Condition: WEAK	
			ELEC. REPAIR COST: {:242} AED
INTERIOR CONDITION			
INTERIOR FAULTS: WARNING LIGHTS IN INFORMATION BOARD		ROOF CEILING CONDITION: AVERAGE	
UPHOLSTERY CONDITION: BAD & DAMAGED		STEERING WHEELS CONDITION: BAD & DAMAGED	
			INTERIOR REPAIR COST: AVERAGE AED
CAR COMPUTER DIAGNOSIS			
MECHANICAL DIAGNOSIS: NO		ELECTRICAL DIAGNOSIS: YES	
			COMP/DIAG REPAIR COST: {:258} AED
TYRES/SUSPENSION CONDITION			
TYRES: AVERAGE		RIMS: AVERAGE	
BRAKES: AVERAGE		SUSPENSION: AVERAGE	
DIFFERENTIAL & BEARING: AVERAGE			
			TYRE/SUS. REPAIR COST: AED